

Model: HT-3000P
Date: May-21-2008
By: H.Silva

DC

Volt Meter	HT-3000P meter	Error full scale (volts)	error %
50	50	0	0.0%
100	100	0	0.0%
150	155	5	3.2%
200	200	0	0.0%
250	250	0	0.0%
300	300	0	0.0%
350	355	5	1.4%
400	400	0	0.0%
450	450	0	0.0%
500	500	0	0.0%
550	550	0	0.0%
600	600	0	0.0%
650	650	0	0.0%
700	690	-10	-1.4%
750	750	0	0.0%
800	800	0	0.0%
850	850	0	0.0%
900	895	-5	-0.6%
950	945	-5	-0.5%
1000	1000	0	0.0%
1050	1045	-5	-0.5%
1100	1100	0	0.0%
1150	1150	0	0.0%
1200	1200	0	0.0%
1250	1245	-5	-0.4%
1300	1295	-5	-0.4%
1350	1350	0	0.0%
1400	1400	0	0.0%
1450	1440	-10	-0.7%
1500	1500	0	0.0%
1550	1550	0	0.0%
1600	1600	0	0.0%
1650	1645	-5	-0.3%
1700	1695	-5	-0.3%
1750	1750	0	0.0%
1800	1795	-5	-0.3%
1850	1845	-5	-0.3%
1900	1900	0	0.0%
1950	1945	-5	-0.3%
2000	1995	-5	-0.3%
2050	2050	0	0.0%
2100	2100	0	0.0%
2150	2145	-5	-0.2%
2200	2195	-5	-0.2%
2250	2250	0	0.0%
2300	2295	-5	-0.2%
2350	2345	-5	-0.2%
2400	2400	0	0.0%
2450	2445	-5	-0.2%
2500	2500	0	0.0%
2550	2550	0	0.0%
2600	2595	-5	-0.2%
2650	2645	-5	-0.2%
2700	2695	-5	-0.2%
2750	2745	-5	-0.2%
2800	2795	-5	-0.2%

